



ASIAN SKY
GROUP

2005
BOMBARDIER
GLOBAL 5000

SN: 9149



AIRCRAFT

YEAR OF MANUFACTURE	2005
SERIAL NUMBER	9149
TOTAL HOURS	4,928 Since New
TOTAL CYCLES	2,363 Since New



TEL: +852 9199 7751
E-MAIL: sales@asianskygroup.com

2005 BOMBARDIER GLOBAL 5000 SN: 9149

AIRCRAFT HIGHLIGHTS

- 240M Completed November 2025 - Bombardier Dallas, USA
- 14 Passenger Configuration
- 5,000 Hours since new
- Engine Enrolled on RRCC Enhanced
- APU Enrolled on JSSI
- Airframe Enrolled on Bombardier Smart Parts Plus
- CAMP Maintenance Tracking Program
- Enhanced Vision System & HUD
- Batch 3 Upgrade, ADS-B Out, FANS-1/A (CPDLC), WAAS / LPV & TCAS 7.1
- No Damage History
- San Marino Registered
- Private Flights Only / Commercial Ops Compliant
- Interior Refurbished 2016, New carpet 2024
- Exterior Paint 2016



2005 BOMBARDIER GLOBAL 5000 SN: 9149

ENGINES & APU

Engines enrolled on RRCC enhanced

- Engine 1
 - ◇ Model: BR710A2-20
 - ◇ Serial Number: 12411
 - ◇ Total Hours: 4,977 Since New
 - ◇ Total Cycles: 2,343 Since New
- Engine 2
 - ◇ Model: BR710A2-20
 - ◇ Serial Number: 12412
 - ◇ Total Hours: 4,982 Since New
 - ◇ Total Cycles: 2,363 Since New
- APU
 - ◇ Model: Honeywell RE220 (GX)
 - ◇ Serial Number: P-249
 - ◇ Program: JSSI
 - ◇ Total Hours: 6,045 Since New

AVIONICS

- Honeywell Primus 2000XP Avionics Package
- Dual Honeywell RNZ-850 ADF
- Honeywell Primus 2000XP IFCS Autopilot
- Triple Honeywell RCZ-833K w/8.33 kHz spacing Communication Radios
- Honeywell SSCVR w/datalink upgrade CVR
- Dual Honeywell DM-850 DME
- Honeywell DU-870 6-tube (color) EFIS
- Honeywell SSFDR FDR
- Honeywell WU-880 Radar
- Honeywell Primus 2000XP IFCS Flight Director
- Dual Honeywell XS-852A TDR
- Dual Honeywell NZ-2000 FMS
- Dual Honeywell FMS-2000 w/LPV GPS
- Dual Collins HF-9031 w/Avtech CSD-714 SELCAL Hi Frequency
- Triple Honeywell LASEREF III IRS
- Dual Honeywell RNZ-851 w/FM immunity Navigation Radios
- Collins ALT-4000 Radar Altimeter
- Collins SAT-2100 ICG Aerocom 3000 Iridium SATCOM
- Honeywell LSZ-860 Stormscope
- Honeywell Mark V EGPWS w/windshear TAWS
- Honeywell TCAS-2000 w/change 7.1 TCAS
- Dual Honeywell RCZ-833M Mode S w/enhanced surveillance Transponder
- Honeywell Primus 880 Weather Radar

2005 BOMBARDIER GLOBAL 5000 SN: 9149

STANDARD EQUIPMENT

- Inertial Reference System
- Flight Data Recorder
- Weather Radar
- SATCOM
- Cockpit Voice Recorder
- Emergency Locator Transmitter
- Terrain Awareness & Warning System
- RVSM
- Traffic Collision Avoidance System
- Dual Flight Management System
- 8.33 channel spacing

ADDITIONAL EQUIPMENT

- Performance Mod: Fuel Tank Mod in 2018 to increase MTOW to 92,500 lbs
- Cockpit: Batch 3.3 upgrades, dual multi-function displays, dual EICAS, dual regime autothrottle systems, integrated electric standby instrument (IESI), triple Honeywell AZ-950 micro air data computers, quad Ametek DA-810 data acquisition units, Teledyne datalink system (ACARS), Artex 406 MHz ELT w/nav interface, quick access recorder, CAIMS, Thales enhanced vision system & heads-up display, ADS-B Out, triple Honeywell IC-800 integrated avionics computers, FANS-1/A, WAAS/LPV (SBAS), ADLS datalink, Honeywell Primus II radio management units
- Crew Accessories: Dual electronic flight bags, electronic pilot checklist (OBDS), Cockpit Printer

MAINTENANCE PROGRAM

- Airframe: Bombardier Smart Parts Plus
- Engine: Rolls Royce Corporate Care Enhanced
- APU: JSSI
- Tracking: CAMP

2005 BOMBARDIER GLOBAL 5000 SN: 9149

INTERIOR

- Refurbished in 2016
- Configuration: Executive/14 passengers
- Seating: Tan leather seating, four forward executive seats, mid-cabin 3-place berthable divan opposite dual executive club seats, aft 4-place conference group opposite dual executive club seats
- Refreshment: Forward galley w/coffeemaker, chilled area & ice drawer, galley annex w/high-temperature oven & microwave
- Cabinetry/Wood: High-gloss dark wood veneer, dual forward foldout tables, mid-cabin foldout table, aft foldout table
- Entertainment: Airshow 400, dual 18.1-inch bulkhead monitors, four 10.4-inch plug-in monitors, dual DVD players, multi-disc CD changer
- Accessories: 110-volt AC outlets
- Lavatory: Forward crew lav & aft lav



EXTERIOR

- New Paint 2016, Air Livery UK
- White w/ blue accent stripes

2005 BOMBARDIER GLOBAL 5000 SN: 9149



2005 BOMBARDIER GLOBAL 5000 SN: 9149



2005 BOMBARDIER GLOBAL 5000 SN: 9149



2005 BOMBARDIER GLOBAL 5000 SN: 9149



2005 BOMBARDIER GLOBAL 5000 SN: 9149



2005 BOMBARDIER GLOBAL 5000 SN: 9149



2005 BOMBARDIER GLOBAL 5000 SN: 9149





ASIAN SKY GROUP

Suite 1509, 15/F, 8 Queen's Road East, Wan Chai,
Hong Kong

TEL: +852 9199 7751
E-MAIL: sales@asianskygroup.com

www.asianskygroup.com